

STABILUS POWERISE®

Installation hints

Durability redefined



Part Number: 131744

Part Number: 407318

Seat Alhambra

Generation: 2010
LH & RH

Note:
Only to be replaced in pairs!

OE Numbers:

7N0 827 851 A
7N0 827 851 B
7N0 827 851 D
7N0 827 851 E
7N0 827 851 F
7N0 827 851 G
7N0 827 851 H
7N0 827 851 J

Stabilus GmbH

Wallerheimer Weg 100
56070 Koblenz
Germany
T +49 261 - 8900-0
info@stabilus.com
www.stabilus.com

This document contains installation hints for Stabilus part number 131744 & 407318

All rights are reserved by Stabilus GmbH.

Please scan QR code for further Stabilus installation instructions.

Remarks

Stabilus Aftersales products are specifically reinforced and enhanced to address common weaknesses of competitive original parts and ensure greater durability.

One common weakness in spindle drives is the routing of cables into the vehicle body, as this can lead to cable breakage over time. For this reason, cable routing is continuously reconsidered during the design of a Stabilus Aftersales Powerise system.

To prevent cable breakage in this particular vehicle, we have decided to introduce two Stabilus replacement parts under the same OE number, which differ only in the way the cables are routed.

For replacement, you will therefore need two Stabilus Powerise drives that must be installed as a pair:

- **131744** - **Left side**
- **407318** - **Right side**